



## Visit Report Sheet

<b>C1027</b>	<b>Visit Details</b> Visit Type: Service Order No: 1353/ Date/Time: 21/06/2024 08:55 Time Completed: 10:03 Consultant: Same As Site Contact: Simon Brooks
AIG Control Systems Ltd Otter Pool Barn West Stowford Barton Barn, West Stowford, Ilfracombe Devon, England EX34 8PJ  07970 538998	<b>Lift Details</b> Asset /Location: Through Floor Lift Make: VM Model: 36 Serial: 12182 Man: 09/2010 S.W.L. 225kg Installed:
<b>Job Details</b> Service due, June 2024	<b>Further Work Required</b>
<b>Completion Notes</b> Carry out a service/inspection to the manufacturer fitted parts and check the condition of the non standard parts fitted.  <b>Parts Used</b>	

### VAT Exemption Certificate - Eligibility declaration by an individual

I declare that i am chronically sick or disabled and suffering from \_

I am receiving a qualifying Product or Service/Maintenance visit supplied to me for my domestic or personal use. I claim relief from Value Added Tax under group 12 of schedule 8 of the Value Added Tax Act 1994. The work has been completed.

**Customer Name:** AIG Control Systems Ltd

**Customer Sign:**

**Date:** 21/06/2024

**Rep Name:** Matt Carling

**Rep Sign:**

**Date:** 21/06/2024



## Service Checks

<p><b>Customer</b></p> <p>AIG Control Systems Ltd Otter Pool Barn West Stowford Barton Barn, West Stowford, Ilfracombe Devon, England EX34 8PJ</p>	<p><b>C1027</b></p>	<p><b>Visit Details</b></p> <p>Visit Code: J1353 Order No: TVMC/21/06/2024 Consultant: Same As Site</p>
		<p>Make: VM Model: 36 Serial: 12182 Man: 09/2010</p>

### Equipment Examined

Check Item	Status	Remarks
What is S.W.L. (Kg)?	Pass	225kg

### Examination Points

Check Item	Status	Remarks
Track & track fixing plates	Pass	Tracks have been extended with the same grade box section. Apart from the paint missing from the extended part of the factory rails, no other defects were found.
Weight test/Load Amount (kg)	N/A	
Pictures taken of weight test?	N/A	
Ancillary fixings	Pass	No defects found
Up & down control	Pass	The lift raises and lowers much slower than the manufacturers recommend speed due to the non standard ram fitted and valve fitted
Remote controls ground and first floor	Pass	Non standard hard wired call stations fitted
Hydraulic pump	Pass	No defects found
Hydraulic hoses	Pass	No defects found
Hydraulic ram & fixings	Pass	No standard ram fitted.
Track guides (car)	Pass	Track guides are wearing down due to the age of the lift and condition of the rails.
Lubricate where necessary	Pass	
Running clearance around lift aperture in travel	Pass	No defects found
Fit of fire seal	N/A	
Abnormal noise or resistance	Pass	Lift is noisy and vibrates and the ram housing rattles when raising and lowering
Mains wiring	Pass	3 core flex running into the spur behind the lift transformer.
Low voltage wiring	Pass	No defects found
Switching modules on back of lift carriage	Pass	No defects found
Up circuit safety cut outs on door, sides, back of lift, floating platform & trap board	Pass	No defects found
Electrical connections	Pass	No defects found
Down circuit safety cut outs on floating platform & trap board	Pass	No defects found

Stop circuit	Pass	No defects found
Battery test 1 readings in v & Ah- Serial Number of Battery	Pass	12.68v - 1.35Ah
Battery test 2 readings in v & Ah- Serial Number of Battery	Pass	12.31v - 1.33Ah
Charging through circuit board	Pass	25v
Internal lighting	Pass	No defects found
Emergency lowering (battery)	Pass	No defects found
Emergency lowering (hydraulic)	Pass	No defects found
User instructions present	Pass	
Labelling including SWL & contact numbers	Pass	

**Consent Request**

Check Item	Status	Remarks
Does client give consent for any pictures taken to be used on social media?	N/A	

**Rep Name:** Matt Carling

**Rep Sign:** 

**Date:** 21/06/2024