

Visit Report Sheet

<p style="text-align: right;">C1027</p> <p>AIG Control Systems Ltd Otter Pool Barn West Stowford Barton Barn, West Stowford, Ilfracombe Devon, England EX34 8PJ</p> <p>07970 538998</p>	<p style="text-align: center;">Visit Details</p> <p>Visit Type: Service Order No: 1465/ Date/Time: 04/03/2025 15:24 Time Completed: 15:39</p>
<p>Job Details</p> <p>Service due,</p>	<p style="text-align: center;">Lift Details</p> <p>Asset /Location: Pool Hoist Make: Oxford Model: Dipper 140 Hydraulic Pool Hois Serial: 66000000347-2016 S.W.L. 140kg Installed:</p>
<p>Completion Notes</p> <p>Service of pool hoist.</p> <p>Parts Used</p>	<p style="text-align: center;">Further Work Required</p>

VAT Exemption Certificate - Eligibility declaration by an individual

I declare that i am chronically sick or disabled and suffering from _

I am receiving a qualifying Product or Service/Maintenance visit supplied to me for my domestic or personal use. I claim relief from Value Added Tax under group 12 of schedule 8 of the Value Added Tax Act 1994. The work has been completed.

Customer Name: AIG Control Systems Ltd

Customer Sign:

Date: 04/03/2025

Rep Name: Mark Pringle

Rep Sign:



Date: 04/03/2025



Service Checks

Customer

C1027

AIG Control Systems Ltd
Otter Pool Barn
West Stowford Barton Barn,
West Stowford,
Ilfracombe
Devon, England
EX34 8PJ

Visit Details

Visit Code: J1465
Order No: TVMC/04/03/2025
Consultant: Same As Site

Make: Oxford
Model: Dipper 140 Hydraulic Pool Hois
Serial: 66000000347-2016

Equipment Examined

Check Item	Status	Remarks
EIN number if present/Asset Number	N/A	
What is S.W.L. (Kg)?	Pass	140kg

Examination Points


Check Item	Status	Remarks
Mast & leg fixings	Pass	
Ancillary fixings	Pass	
Up and down control	Pass	
Condition of lifting boom	Pass	
Actuator mounting bolts	Pass	
Life cycle of actuator (use calculator to approximate usage)	Pass	
Retaining pins	Pass	
Use 50mm implement to check 4mm hole at base of mast is clear of debris	Pass	
Check outer white surface of mast for corrosion/blistering/bubbling of coating	Pass	
Spreader bar	Pass	
Traverse castors & brakes	N/A	
Lubricate where necessary	N/A	
Abnormal noise or resistance	Pass	
Mains wiring to charger	N/A	
Low voltage wiring	N/A	
Battery test 1 readings in v & Ah- Serial Number of Battery	N/A	
Battery test 2 readings in v & Ah- Serial Number of Battery	N/A	
Charger test readings v	N/A	
Up limit switch	N/A	
Down limit switch	N/A	
Emergency lowering manual	N/A	
Emergency stop switch	N/A	

Hoist cover and head protection cover	Pass	
User instructions present	Pass	
Labelling inc SWL & contact numbers	Pass	
Weight test (140kg load MUST be carried out on Dipper Hoist)	N/A	
Pictures taken of weight test?	N/A	
After load test check for any structural damage/ deformation of the mast	N/A	

Consent Request

Check Item	Status	Remarks
Does client give consent for any pictures taken to be used on social media?	N/A	

Rep Name: Mark Pringle

Rep Sign: 

Date: 04/03/2025

